



# Logo Placements

## 6314 RW, Work Trousers+

### Recommended logo placements

#### Heat seal & Embroidery

- 11 Rear side of left leg (calf), centered between knee and lowest point of the trousers
- 16 Rear side of right leg (calf), centered between knee and lowest point of the trousers
- 28 Rear side of right leg, centered between knee and lowest point of the trousers
- 34 Rear side of left leg, centered between knee and lowest point of the trousers
- 100 Right leg, centered above kneeknee pocket, maximum size 120x40 mm

#### Heat seal

- 18 Centred at right hip-pocket, maximum size 120x120 mm
- 31 In the corner of right front pocket, maximum size 120x120 mm

Placement 28 and 34 maximum size, for embroidery 80x220 mm and for heat seal 200x220 mm

Placement 11 and 16 maximum size, for embroidery 80x220 mm and for heat seal 200x220 mm

Add



B after the placement and it will be below the (1B)

Y and it will be turned from bottom to top

Z after the placement and it will be turned from top to bottom

